
















Vehicle information			
Make:	HONDA	License:	RX4401
Gearbox:		Body color:	
Model:	HONDA E	VIN:	JHMZC7840MX201745
Fuel type:		Power:	113 kW
Version:	HONDA HONDA E 35.5 KWH ADVANCE 17 INCH	First registration	10/06/2022
Mileage:	33024 km	N° of doors:	

Damage summary		Total Net Cost (exVAT) 0.00 EUR
Left	1	Right1

Commercial pictures







Options according to the inspector

No option checks information found



Damages

Alloy rim RR

Scratch(es)

-

Right

Net Cost 0.00 EUR




Door RL

Scratch(es)

-

Left

Net Cost 0.00 EUR



Tyres	
No tyre information found	

Checks			
Category	<b>VS</b>	Certificate of Conformity	<b>Yes</b>
Fuel Level	<b>50</b>	Luggage cover	<b>Yes</b>
Maintenance	<b>OK</b>	Maintenance	<b>18/06/2025</b>
Maintenance	<b>350.0</b>	Maintenance	<b>350 jours</b>
Number of charging cables (normal)	<b>2</b>	Number of keys total	<b>2</b>
Number of seats	<b>4</b>	Registration Certificate	<b>Yes</b>
Registration Certificate	<b>Original</b>	Repair kit	<b>No</b>
Service book	<b>Yes</b>	Spare wheel	<b>No</b>
Type of tires	<b>All seasons</b>	User's manual	<b>Yes</b>

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.