

## HYUNDAI Nexo Nexo VIN NO KMHJ8816FLU006392

Registration Number 6FLU006392



**MOT Date** 

Number of Owners

42590

Odometer Reading

**2**025-07-01

2

**P**2

Last Service

Last Service Mileage

First Registration Date

Number of Keys

Country First Registered

**2**024-09-27

**=** 2020-07-09

Germany

### **Inspection Report Summary**

Customer BCA Online Report Number P20250512093550

Inspection Date / Place 2025-05-12 / BCA Oberndorf Cosmetic Grade 2

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Hydrogen	Road Worthy	Yes
Colour	Cream	Engine Size (cc)	
Engine Size		No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grey Two tone	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			



















































# Equipment

Tow ball	360°camera	Alloys wheels	Bluetooth telephone interface
Digital Radio	Front parking sensors	Remote central locking	Satellite navigation
Split folding rear seats	Sunroof	Electrically folding wing mirrors	Leather steering wheel
Radio	USB Socket	Airbag Status	Anti-lock braking
Cruise control	Digitaldashboard	Remote adjusting wing mirrors	Roof rails
Seatventilation	Stability control	Electrically adjustable seats	Electrictailgate
LED Headlamps	Rear parking sensors		


# **Equipment Details**

Tow Ball Type	Detachable	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	19	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front and Rear	Sunroof Type	Tilt/Slide Glass


# Wheels & Tyres

Right Front Tyre Depth	7	Left Front Tyre Depth	7
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7
Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	6

#### Cosmetic Damage




14	Door / Back Left	Paint / Scratch / Scuff
15	Interior door handle Back right	Interior / Scraped



1. Luggage Space Cover / Back Interior / Scraped -

2. Tailgate Upholstery / Back Interior / Scraped -



3. Windshield / Front Glass Break / Impact -

4. Panel Filling / Front Left Interior / Scraped -




5. Pillar / Back Left Paint / Scratch / Line -

6. Roof Bodywork / Dent / Hail Area -




7. Hood Bodywork / Dent / Hail Area -

8. Panel Filling / Front Right Interior / Scraped -



9. Backrest Cover / Front Right Interior / Scraped -

10. Door / Front Right Bodywork / Dent / Dent -



11. Door / Front Right Bodywork / Dent / Dent -

12. Bumper / Back Paint / Scratch / Scuff -



13. Bumper / Back Paint / Scratch / Scuff -

14. Door / Back Left Paint / Scratch / Scuff -



15. Interior door handle Back right Interior / Scraped -

#### **Mechanical Condition**

Control Lights			
Display Defect	•	Service Light	•
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Airbag Warning Light	•	Oil Pressure Warning Light	<b>⊘</b>
Brake Warning Light	•	Power Steering Warning Light	•
No Dashboard Lights	<b>⊘</b>		
Equipments Test			
Central Locking	•	Electric Windows	•
Navigation System	•	Audio Equipment	•
Parking Sensors / Cameras Functioning	•	AC / Heating System	<b>⊘</b>
Engine			
Engine Status / EML	•	Engine Starts	•
Levels			
Brakes Fluid	•		
Test Drive Inspection			
Steering Wheel			
Steering   Noise / Anomaly		<b>⊘</b>	
Brake			
Brake System Anomaly		•	
General			
Test Driven Status		Not Performed	
Engine			
Engine Noise		<b>②</b>	
<ul> <li>No troubles detected, good condition or correct tests, according to vehicle age and mileage</li> <li>Damages or malfunction detected that requires repairs by the buyer</li> <li>Not applicable</li> <li>Not tested</li> </ul>			

#### Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

<u>User Guide</u>