

Vehicle details

VIN	W1N253311 1F937747	Brand	MERCEDES	Maintenance date	-
Licence Plate	I2746AU	Model	GLC Coupe 300de 4matic Automatik AMG-Line 14	Maintenance mileage	-
Registration date	06/04/2021	Year	1000	Exterior Color	Silver Metallic
Odometer	192 345 km	Engine size	1950	interior Color	Black
Fuel	Diesel	Body Type	SUV CrossOver	Next technical inspection	01/04/2026
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	04/08/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Sliding roof	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓

Removable element



Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 235/55/19 V Summer 3.2 mm		Pirelli 235/55/19 V Summer 3.3 mm	
Pirelli 255/50/19 V Summer 4.6 mm		Pirelli 255/50/19 V Summer 4.5 mm	

Exterior

1		Part Tyre Position Front left Damages Cut Severity - Repair mode Replace	2		Part Windscreen Position - Damages Stone impact Severity - Repair mode For info
3		Part Bonnet Position - Damages Dent & Chips Severity - Repair mode Repair	4		Part Bumper Position Front Damages Scratched Severity - Repair mode Repair
5		Part Wing moulding Position Front left Damages Scratched Severity - Repair mode Replace	6		Part Alloy wheel 19" Position Front left Damages Scratched Severity - Repair mode Replace
7		Part Door Position Front left Damages Dent & Chips Severity - Repair mode Repair	9		Part Door sill Position Back left Damages Scratched Severity - Repair mode Repair
12		Part Tailgate / Boot door Position - Damages Dent & Chips Severity - Repair mode Repair	13		Part Bumper Position Back Damages Scratched Severity - Repair mode Repair
14		Part Door Position Back right Damages Dented Severity - Repair mode Repair	15		Part Door Position Front right Damages Scratched Severity - Repair mode For info
16		Part Alloy wheel 19" Position Front right Damages Scratched Severity - Repair mode Replace			

Interior damage

8

A close-up photograph of a car's interior door panel, showing the fabric door lining and the handle area. The panel appears to be in good condition.

Two green dots.

Part	Fabric door lining
Position	Back left
Damages	Deformed
Severity	-
Repair mode	Replace


10

A photograph of a car's front left leather seat. The seat shows signs of wear, including a cut in the leather.

Two green dots.

Part	Leather seat
Position	Front left
Damages	Cut
Severity	-
Repair mode	Replace

11

A photograph of the back of a car's front left leather seat. The seat shows signs of wear, including a cut in the leather.

Two green dots.

Part	Leather seat back
Position	Front left
Damages	Cut
Severity	-
Repair mode	Replace

17

A photograph of a car's interior door panel, showing the fabric door lining and the handle area. The panel appears to be in good condition.

Two green dots.

Part	Fabric door lining
Position	Back right
Damages	Deformed
Severity	-
Repair mode	Replace

Others

18



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

19



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint