

Inspection Protocol



VW TRANSPORTER T30 2.0 TDI

Vehicle information

License plate	XEN623	Inspected by	A.H.
Year model	2018	Date of inspection	2025-03-19
Manuf. year/month	2018-02	City	Falkenberg
First day in traffic	2018-02	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	230 770 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	Manuell	Summer tires	16" plåtfälg 5/5/5/4
Engine effect	75 kW	Winter tires	plåtfälg dubbat 5/7/7/6

Damages

Location	Damage	Comments	Costs excluding VAT
Other, Other	Other	Gnisslande rem	-
Other, Other	Other	Komplett bilmapp saknas	-
Door, Lef side mirror	Paint retouch traces		0 €
Tak, A-pillar	Stenskott/ repa	Vänster	0 €
Other, Other	Other	Sliten ratt	-
Inredning, Drivers seat	Tears		150 €
Wing, Rear left	Scratches below 30 mm	Rost fläck	60 €
Bumper, Rear	Cargo scratches	Revor	150 €
Boot lid, Boot lid	Dents below 30 mm		60 €
Recond	Interior	Klädsel tvätt passagerare säte	60 €
Door, Righ side mirror	Scratches 30-100 mm		80 €
Other, Other	Regskylt fram inbuktningar		10 €
Bonnet	Chip		60 €
Glass, Windshield	Pitted windshield		510 €
Bumper, Front	Cracks small (max 30 mm)	Samt Boxerings locket saknas	70 €

Total excl. VAT	1 210 €
-----------------	---------

Service occasions

1500-MIL, 20000-MIL

Images

[See all images in large format](#)



















Dörr Vänster backspegel Lackbättring 50 kr



Tak A-stolpe Stenskott/ repa Vänster 50 kr



Övrigt Övrigt Övrigt Sliten ratt



Inredning Vänster framstol Revor 2 000 kr



Skärm Vänster bak Repor under 3 cm Rost fläck 800 kr



Stötfångare Bak Lastrepor Revor 2 000 kr



Bagagelucka Bagagelucka Bucklor under 3 cm 800 kr



Rekond Invändig Klädsel tvätt passagerare säte 800 kr



Dörr Höger backspegel Repor 3-10 cm 1 100 kr



Övrigt Övrigt Regskylt fram inbuktningar 100 kr



Stötfångare Fram Sprickor små, under 3 cm Samt Boxerings locket saknas 1 000 kr



Motorhuv Stenskott 800 kr



Glas Vindruta Blåstrad ruta 7 000 kr



