MAC▲DAM

OPEL Corsa: 2CKW001

Vinnumber:	VXKUPHNSSN4310509	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk 5D/P Auto-8
First Registrationdate:	30/08/2022	Fiscalpower:	
Expertise Mileage:	20662	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Parking lot	d044
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol		
Number of seats	5		
Bodywork	Clean		
Registration Certificate Car (BE)	Yes		
Number of doors	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Interior	Clean		

Options

Airco manual		Front parking sensors	
Rims alloy		Radio	
Number of keys total	2	Rear parking sensors	
Windows electric F			
Steering wheel multifunctional			
Seats F heated			
Number keys remote	2		
Windows electric R			
Cruise Control			

Limited Technical Inspection

Engine startingtime	OK	Sound engine	OK
Idle position	OK	Transmission	OK
Exhaust gass	OK	Clutch test	OK

Degree of wear

Summer tyres:	195/55/16/91 H			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Tyre size RR	195/55 R 16 91 H
Tyre make RR	259
Tyre profile depth FL	5.0
Tyre type FR	All Seasons
Tyre size FL	195/55 R 16 91 H
Tyre make FL	259
Tyre profile depth RL	5.0
Tyre type RR	All Seasons
Tyre make RL	259
Tyre size RL	195/55 R 16 91 H
Tyre type FL	All seasons
Tyre profile depth FR	5.0
Tyre type RL	All seasons
Tyre make FR	259
Tyre size FR	195/55 R 16 91 H
Tyre profile depth RR	5.0

Assistance equipment

Number of charging cables (rapid charge)	0	Compressor	Yes
Repair kit	Yes		
Number of charging cables (normal)	0		

## Door panel FL, Scratch(es), Acceptable

Centre console, Scratch(es), Acceptable


Door panel FR, Scratch(es), Acceptable

Bumper F, Bad repair, Repair and paint (complete)

Bonnet, Dent(s), Paintless dent repair

Door FL, Bad repair, Spot repair

Wing RL, Bad repair, Spot repair

Wing FL, Dent(s), Acceptable

Bumper R, Dent(s), Acceptable

Door FR, Dent(s), Paintless dent repair

Door RR, Dent(s), Spot repair

Wing RR, Dent(s), Acceptable

Roof, Dent(s), Paintless dent repair