



RENAULT Kangoo Express: 1XHX961

Vinnnumber:	VF1FW51H162983475	Versionname:	KANGOO EXPRESS MAXI DSL - 2013 1.5 dCi Energy Grand Confort (EU6) 66kw/90pk 5D/P M5	
First Registrationdate:	10/01/2020	Fiscalpower:		
Expertise Mileage:	165565	Power Kw:	66	
Bodytype:		Body colour	White	
Gearbox:	MAN 5 VIT	Type of rims (mounted)	Steel	
Transmission:	Front	Parking lot	d220	
Fueltype:	Diesel			
Number of doors	5			
Number of seats	2			
Number head rests	2			
Type of rims (mounted)	Steel			
Certificate of Conformity	Yes			
Category	Light Commercial Vehicle			
Registration Certificate Car (BE)	Yes			
Bodywork	Clean			
Interior	Dirty			

Options

Number of keys total	2	Radio
Number keys remote	2	Rear parking sensors
Windows electric F		
Airco manual		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

195/65/15/91 T				
Winter tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 6 mm
Tyre profile depth FL	4.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	6.0			
Tyre size FL	195/65 R 15 91 T			
Tyre size FR	195/65 R 15 91 T			
Tyre size RL	195/65 R 15 91 T			
Tyre size RR	195/65 R 15 91 T			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	2477			
Tyre make FR	2477			
Tyre make RL	2484			
Tyre make RR	2484			

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Door panel FR, Scratch(es), Smart repair



Centre console, Scratch(es), Smart repair



Glove box, Scratch(es), Acceptable



Floor covering FR, Scratch(es), Acceptable



Armrest, Scratch(es), Acceptable



Bumper F, Dent(s) and scratch(es), Replace



Bonnet, Dent(s), Acceptable



Wheel cover FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Broken, Replace



Wing RL, Dent(s), Repair and paint (complete)



Boot door lining L, Crack, Replace



Boot door lining R, Crack, Replace



Boot door panel RL, Dent(s), Acceptable



Boot door panel RR, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Acceptable



Wheel cover FR, Crack, Replace




Wheel cover RR, Missing, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)





Door RR, Dent(s), Acceptable



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Bodywork, Scratch(es), Acceptable





Roof, Rust, Acceptable

