


Vehicle details

VIN	VF3MCYHZR JL089924	Brand	PEUGEOT	Maintenance date	-
Licence Plate	G686US	Model	5008 SUV GT-Line 1.5 BlueHDi 130 S&S EAT8 96K	Maintenance mileage	-
Registration date	14/01/2019	Year	1000	Exterior Color	Green Metallic
Odometer	78 494 km	Engine size	1499	interior Color	Black
Fuel	Diesel	Body Type	SUV CrossOver	Next technical inspection	01/01/2025
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	13/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Panoramic roof	✓
7 seater	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓

Removable element



Technical Document

Spare key	✓
Remote key	✓

Tyres

Winter kit

Michelin 215/65/17 H Winter 5.9 mm		Michelin 215/65/17 H Winter 5.0 mm	
Michelin 215/65/17 H Winter 5.0 mm		Michelin 215/65/17 H Winter 5.7 mm	

Exterior

2



●●●

Part	Bonnet
Position	-
Damages	Improper repair
Severity	-
Repair mode	Repair

3



●●●●

Part	Door sill
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

4



●●

Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

5



●●●●●●●

Part	Roof
Position	-
Damages	Hail damaged
Severity	-
Repair mode	Repair

6



●●●●●

Part	Door sill
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



●●●

Part	Door
Position	Back right
Damages	Dented
Severity	-
Repair mode	Repair

8



●●

Part	Door sill
Position	Front right
Damages	Dented
Severity	-
Repair mode	Repair

9



●●

Part	Exterior door mirror shell
Position	Right
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

1



Part	Seat complete
Position	Front left
Damages	Broken
Severity	-
Repair mode	Replace

Others

10



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

11



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks