



BMW X3: L174GS

Vinnnumber:	WBATS110809G63162	Versionname:	X3 xDrive 30eA 215kW
First Registrationdate:	21/05/2021	Fiscalpower:	
Expertise Mileage:	112849	Power Kw:	135
Bodytype:		Body colour:	Schwarz Unilak
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	836
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors
		Hook

Degree of wear

	245/50/19/105 V			
Winter tyres:	Fr.L.	Bridgestone: 4,1 mm	Fr.R.	Bridgestone: 4,4 mm
	Re.L.	Bridgestone: 7,2 mm	Re.R.	Bridgestone: 7,2 mm
Tyre profile depth FL	4.1			
Tyre profile depth FR	4.4			
Tyre profile depth RL	7.2			
Tyre profile depth RR	7.2			
Tyre size FL	245/50 R 19 105 V			
Tyre size FR	245/50 R 19 105 V			
Tyre size RL	245/50 R 19 105 V			
Tyre size RR	245/50 R 19 105 V			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	255			
Tyre make FR	255			
Tyre make RL	255			
Tyre make RR	255			

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Malfunction, Not functioning (well), Diagnosis



Interior, Smell, Ozone treatment



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Polish



Wing RL, Scratch(es), Polish



Wheel arch cover FL, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Polish



Luggage compartment cover, Missing, Replace



Bumper R, Crack, Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Tow bar (fixed), Deformed / Strained, Replace



Bodywork, Paint measurement, Acceptable

