



BMW X2: 1XLQ011			
Vinnumber:	WBAYK110405P99900	Versionname:	X2 sDrive16d DCT 85kW/116pk 5D/P Auto-7
First Registrationdate:	4/02/2020	Fiscalpower:	
Expertise Mileage:	1	Power Kw:	
Bodytype:		Body colour	Orange
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Back	Parking lot	Takel 15
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Very dirty		
Interior	Dirty		

Options			
Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Fog lights (front)	
Cruise Control			
Steering wheel multifunctional			
Airco electronic			
Rims alloy			

Limited Technical Inspection			
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Transmission	NOT OK
Exhaust gass	NOT OK		

Degree of wear				
	225/55/17/97 H			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				4.
Tyre profile depth FR				3.
Tyre profile depth RL				7.
Tyre profile depth RR				6.
Tyre size FL				225/55 R 17 97
Tyre size FR				225/55 R 17 97
Tyre size RL				225/55 R 17 97
Tyre size RR				225/55 R 17 97
Tyre type FL				Winte
Tyre type FR				Winte
Tyre type RL				Winte
Tyre type RR				Winte
Tyre make FL				25
Tyre make FR				25
Tyre make RL				25
Tyre make RR				25

Assistance equipment			
Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		



GPS, Not functioning (well), Acceptable



Interior, Dirty, Cleaning



Engine, Not functioning (well), Check



Composite repair kit, max. 1 m², Missing, Replace



Compressor, Missing, Replace



Boot carpet, Chemical pollution, Replace



Tailgate / Boot, Deformed / Strained, Acceptable

