

Date
Inspection
no.
Performed

Department

79731

Odense

RSJ

FDM Test & Bilsyn

31-07-2025 15:42

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CL52181	Stelnummer	WV1ZZZ7HZKH131664		
Mærke	VOLKSWAGEN	Model	TRANSPORTER	Version	2.0 TDI BMT 114 KASSEVOGN KORT
Karrosseritype		Farve		Reg. dato	08-07-2019
Drivkraft	Diesel	Drivlinje	Front wheel drive	Geartype	Manuel
KM. stand	122191	Antal nøgler	1	Kontraktnummer	1009950
Afleveringsdato	29-07-2025				

Udvendige billeder











Date
Inspection
no.
Performed

Department

79731

RSJ

FDM Test & Bilsyn Odense

31-07-2025 15:42

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Continental	215/65-16	03 mm	Helårs
Venstre, Bag	Continental	215/65-16	06 mm	Helårs
Højre, Bag	Continental	215/65-16	06 mm	Helårs
Højre, For	Continental	215/65-16	02 mm	Helårs

Ekstra hjul

Ekstrahjul tilstede Nej

Position	Mærke	Dæktype
Ekstrahjul		

Reservedæk og rep. kit

Rep. kit tilstede Findes ikke Reservehjul tilstede Ja

Position	Mærke	Størrelse	Slidbane	
Reservehjul		/-		





31-07-2025 15:42 Date Inspection no.

by

Department

Performed

FDM Test & Bilsyn Odense

79731

RSJ

Præsentationsbilleder

























Date
Inspection
no.
Performed
by

Department

79731

RSJ

FDM Test & Bilsyn Odense

31-07-2025 15:42

Mangler / Tilstand

Ref	Sted	Del	Туре	Handling
#1	Nøgle	Nøgle	Ikke tilstede	K5
#2	Lille folie	Lille folie	Ikke afmonteret	K4



Sted Nøgle
Del Nøgle
Type Ikke tilstede



Skader

Ref	Sted	Del	Туре	Handling
#1	Forrude	Rude	Stenslag	K4
#2	Bagklap	Fløjdør Højre	Mekanisk fejl	K4




Date 31-07-2025 15:42 Inspection 79731

Performed

RSJ

Department FDM Test & Bilsyn Odense



Sted	Forrude
Del	Rude
Туре	Stenslag



Sted	Forrude
Del	Rude
Туре	Stenslag



Sted	Bagklap
Del	Fløjdør Højre
Туре	Mekanisk fejl

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl

Fabriksudstyr

- Fixed towbar (including trailer stability control)	- Without additional storage compartments in driver's cab	- Covering sliding door panel
- Electrically adjustable and heated exterior mirrors	- Without curtains	- Passenger airbag can be deactivated
- Convex exterior mirror, left	- Transport protection measures without surface protection film	- Driver/passenger side airbags
- Convex exterior mirror, right	- Folding roof frame handles	- Anti-lock braking system (ABS)
- Black exterior mirror housing and door handles	- Without sliding door on left, in loading/passenger compartment (closed side wall)	- Front-wheel drive
- Headlight range control	- Without decorative strip and decorative trim	- Convex exterior mirror, left



Date 31-07-2025 15:42
Inspection 79731
Performed by RSJ
Department FDM Test & Bilsyn Odense

- Convex exterior mirror, right	- Hinges for rear doors/tailgate in standard design	- Daytime running lights (permanently on during operation)
- Rubber floor covering in driver's	- Without rear compartment heating	- Transporter lettering
cab	duct/ventilation duct	set
- Electronic stability program (ESP) with brake assist, ASR/ABS, EDS, and hill start assist	- Sun visors with ticket pocket on driver's side and airbag label on front passenger sun visor	- Heat-insulating glass (green)
- Brake assist system (HBA)	- Without surround monitoring system "Front Assist" and without City Emergency Braking function	- Laminated front windshield with heat- insulating glazing
- Multi-collision brake system	- Without C rails	- Without interior safety mirror
- Tinted laminated windshield	- Without mud flaps	- Without navigation system
- 5-speed gearbox	- Without additional exterior dust protection seals	- "Composition Colour" radio with 5" touchscreen
- Lockable glove compartment	- Without entry grab handle on A-pillar	- "Composition Colour" radio
- Interior filter: pollen filter	- Without socket	- 4 speakers: 2 tweeters, 2 woofers
- Body type: panel van	- Without speed limiter	- USB interface (also compatible with iPod/iPhone/iPad)
- Normal roof version	- Without SD card for navigation	- Mobile phone interface
- Fuel tank: 70 liters	- Instrument lighting	- ParkPilot in front and rear
- Height-adjustable steering column (steering wheel)	- Without Blind Spot Assist "Side Assist"	- Tire pressure monitoring system
- 2.0 liter engine - 84 kW TDI	- Without 2nd battery	- Cruise control
- Non-smoker package	- Without light assistant	- Airbags for driver and front passenger, passenger airbag deactivation, belt tensioners for outer seats
- Wheelbase 3000 mm	- H4 halogen headlights	- Dashboard with narrow center console and 2 cup holders
- Particulate filter	- Windshield wiper interval control	- High partition without window and 8 tie- down rings for cargo securing
- Low emission according to Euro 6 standards	- Rear lights in standard design	- Rubber floor covering in driver's cab
- Sliding door on right side for loading/passenger compartment	- Rear fog light	- Universal floor in passenger/cargo area





Date 31-07-2025 15:42
Inspection 79731
Performed by RSJ

Department

FDM Test & Bilsyn

Odense

- Power steering	- Without fog lights	- Comfort ceiling in driver's cab, hardboard ceiling in passenger/cargo area
- Seat covering / upholstery: fabric	- Without headlight cleaning system	- Side lining in hardboard panels in passenger/cargo area (half-height for vehicles with window cutouts)
- Engine start/stop system	- Single-tone horn	- Water auxiliary heating with programmable parking heater function
- Daytime running lights	- Standard interior lights concept in passenger/cargo area	- Water auxiliary heating with programmable parking heater function
- Front door storage compartments	- Without roof blinker lights	- Air conditioning "Climatic" in driver's cab
- Interior lining in loading/passenger compartment: half- height hardboard	- Without recognition lights	- Refrigerant R134a
- Electronic immobilizer	- Without revolving warning lights	- Dust and pollen filter
- Heat-insulating glass	- Without tachograph	- Water auxiliary heating with programmable parking heater function
- Fixed towbar	- Without multi- function display and without onboard computer	- Heated seat for driver's seat, left, adjustable
- Composition Colour audio system (Radio/CD player, MP3 playback)	- Without multimedia in vehicle	- Fabric seat covers, "Austin" design
- Universal wooden floor in loading/passenger compartment	- Operating voltage 12 V	- Height adjustment for left single seat in driver's cab
- Electric package 1	- Category 3	- Left seat, in the 1st row
- Front and rear parking assist system	- Transporter	- Double front passenger seat on right, with storage compartment, in the 1st row
- Folding remote key (4)	- Without storage space	- Lumbar support for left single seat in the 1st row (manually adjustable)
- Cruise control	- Component set without country- specific construction requirements	- Armrest for left seat in driver's cab
- Rear wing doors without glazing	- Supplement to operating permit	- Headrests, front and rear, height-adjustable





31-07-2025 15:42 Date Inspection 79731 no. Performed RSJ by FDM Test & Bilsyn

Odense

Department

- Interior unlock for rear hatch/rear wing doors	- 4-cylinder turbodiesel engine 2.0 L/84 KW TDI Common Rail basic engine: T29	- Electric windows
- Climatic air conditioning (driver's cab)	- No special edition	- Central locking with remote control
- High partition without window	- Without extended warranty	- Central locking with remote control
- Truck registration	- Without online services	- Tailgate closing with interior unlocking function
- Bluetooth mobile phone interface	- Without fatigue detection	- 2 folding flip keys, 1 fixed key
- Tire pressure monitoring system	- Without front socket	- Rear wing doors without window cutouts
- Spare wheel in driving condition	- Without maintenance contract	- Rear wing doors without windows
- Seats in driver's cab: Armrests, driver's seat	- No special vehicle, standard edition	- Sliding door right, in loading/passenger compartment
- Seats in driver's cab: Double front passenger seat with storage compartment	- Basic equipment version	- Warning buzzer and light for unfastened driver's safety belt
- Seats in driver's cab: Heated driver's seat	- Without right closing aid	- Step illumination in passenger/cargo area
- Seats in driver's cab: Height-adjustable driver's seat	- Without rear tailgate closing aid	- Electronic immobilizer
- Seats in driver's cab: Lumbar support for driver's seat	- Without left closing aid	- Reinforced tie-down rings for securing cargo (ISO 27956)
- Central locking with remote control	- Empty weight range 1	- Tool kit and jack
- Permissible total weight 3.00 t	- without incline	- Hill start assist
- Standard production process	- Standard front axle weight	- 16" chassis with 16" brake system
- Manual transmission	- Standard rear axle weight	- 4 steel wheels 6.5 J x 16 in 20-hole design
- Front axle weight classification range 4	- Without interface for external use	- Short wheelbase
- With special sticker	- Titanium black/Titanium black- Moonrock Grey/Black	- All-season tires 215/65 R 16 C 106/104 T, low rolling resistance
- Without special stickers/signs	- Without awning	- Steel spare wheel with driving surface
- Without floor mats	- Without emblems (interior)	- All-season tires 215/65 R 16 C 106/104 T, low rolling resistance
- User manual in Danish	- Battery/generator	- Power steering and safety steering column, height and length adjustable





Date 31-07-2025 15:42
Inspection 79731
Performed by RSJ

Department FDM Test & Bilsyn Odense

- Front axle weight classification range 2, only installation control no demand forecast	- Without paging function	- Electronic Stability Program, ABS, ASR (with deactivation button), EDS, hill start assist, and brake assist
- Standard suspension and damping	- Volkswagen AG, Hannover	- Hill start assist
 Vehicle classification differentiation -7E0- 	- Without child seat	- Battery 520A (92Ah)
- Type plate for commercial vehicle with EU type approval, with weight specification, with COC papers	- Without storage package	- Battery 520A (92Ah)
- Warning signs without country group	- Without voice control	- 180 A three-phase generator
- Standard air filter	- Without chrome package	- 5-speed manual gearbox
- Steering wheel	- Without TV Reception/Digital Radio Reception	- Euro 6b emission standard (with diesel particulate filter for TDI)
- Center wheel cap	- Special Price Tool Pack	- Fuel tank with 70 l capacity
- Wheel bolts without wheel locks	- Fleet Order	- Not hot country
- Without first aid kit and warning triangle	- 4-cylinder diesel engine 2.0L Aggr. 04L.G	- Standard climate zones
- Without insulating box and without glove compartment cooling	- Instrument cluster (km/h); Displays for speed, total/daily distance, RPM, fuel level, and time	- Start-stop system with brake energy recovery
- Without mechanical rear axle differential lock	- Tires without specific brand specification	- CXHB
- Higher initial fuel filling (16 I)	- Extension collector panel van	- Type approval country Denmark
- Transport mode activated	- Description not found	- Denmark
- Gray bumpers	- Right-hand traffic	- Armrest on driver's seat
- Standard sound insulation measures	- Left-hand drive	- Extra key
- Loading edge protection (inside) in plastic	- LNFZ version	- Lumbar support on driver's seat
- Without modular seat fastening	- Extended maintenance interval	- "Composition Colour"
- Without additional tires	- Service indicator 40000 km or 2 years (variable)	- Climatic
- Without additional ISOFIX and Top Tether child seat anchoring	- Without seats in the 2nd row	- Parking heater





31-07-2025 15:42 Date Inspection 79731 no. Performed RSJ by FDM Test & Bilsyn

Odense

Department

- Spare wheel	- Without seats in the 3rd row	- Without leather trim level
		- Without glass
- Preparation for trailer	- Without seats in the	sliding/tilting sunroof
hitch	4th row	in driver's cab
	- Without table (for	
- Remote central locking	Multivan CL and HL	- Door panel
	with two sliding doors:	unpainted
	guide rails for table on	apaca
	floor available)	
	- Without side window	
- Tailgate with window	openings in	 Without roof railing /
· unguto · · · · · · · · · · · · · · · · · · ·	passenger/cargo area,	roof load carrier
	right	
- Tire pressure control	 Without child safety 	Med
system	lock in passenger	- Without luggage
oyote	compartment	compartment cover
	- Electric package I:	
	electric windows and	- Without additional
- Power windows and	electrically	interior sound
power mirrors	adjustable/heated	insulation
	exterior mirrors	
	- Non-smoking edition	
- Cruise control	(12 V socket in	- Without sunshade
0.0.00 000.	dashboard)	······································
		- Without windows
- Height-adjustable driver's seat	- Without seats in the	(closed side wall) in
	3rd row	loading area, front and
		rear left
- Heatable driver's	- Permissible total	
seat	weight 3,000 kg	- Without rear window
Cour	- Normal roof version	
	(with attachment	
- Passenger seat with	points for roof rack	
storage compartment	systems: 8 on short	- Without front airbags
	wheelbase, 10 on long	
	wheelbase)	
- Low rolling		- Without roof luggage
resistance all-season	- Panel van	net and storage/value
tires 215/65R16		compartment
	- Normal roof version	
- Trailer hitch	(with attachment	- Universal wooden
	points for roof rack	floor in loading area
	systems: 8 on short	with edge protection,
	wheelbase, 10 on long	rear
	wheelbase)	
- Candy White uni paint	- Candy White	- Without special body measures
	- Unpainted radiator	
	grille, with a chrome	- Carrier frequency
	trim	433.92 to 434.42 MHz

