


DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZ3CZ ME094614	Brand	VOLKSWAGEN	Maintenance date	04/03/2022
Licence Plate	STU57K	Model	Passat-Variant-CB5-2019	Maintenance mileage	30 754 km
Registration date	30/03/2021	Year	2021	Exterior Color	Other
Odometer	146 705 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	13/05/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Spare key	✗
Charging kit	✗
Service manual holder	✓
User manual	✓
Key	✓
Remote key	✓
Type 2 charging cables	✓

DEKRA Automotive Solutions

Tyres

Goodyear 215/55/17 T Summer 8.0 mm		Goodyear 215/55/17 T Summer 8.0 mm	
Goodyear 215/55/17 W Summer 7.0 mm		Goodyear 215/55/17 W Summer 7.0 mm	

Winter kit

Michelin 215/55/17 T Winter 8.0 mm		Michelin 215/55/17 T Winter 8.0 mm	
Michelin 215/55/17 T Winter 8.0 mm		Michelin 215/55/17 T Winter 8.0 mm	

Damages

1



Part	Charging kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

3



Part	Complete service track record
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum

4



● ●

Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

5



● ● ●

Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

6



● ● ● ●

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

7



● ●

Part	Sill
Position	Right
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

8



● ●

Part	Bumper grille
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

9



● ●

Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Polishing

10



● ●

Part	Door sill
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

DEKRA Automotive Solutions

11		Part Position Damages Severity Repair mode	Wing Back left Dented - For info
12		Part Position Damages Severity Repair mode	Bumper Back Scratched - For info
13		Part Position Damages Severity Repair mode	Tailgate / Boot door Back Dented - Lumpsum repair
14		Part Position Damages Severity Repair mode	Wing Back right Scratched - For info
15		Part Position Damages Severity Repair mode	Door Back right Dented - For info
16		Part Position Damages Severity Repair mode	Door Front right Dented - For info
17		Part Position Damages Severity Repair mode	Door sill Front right Dented - For info
18		Part Position Damages Severity Repair mode	Alloy wheel Front right Scratched - For info
19		Part Position Damages Severity Repair mode	Bonnet Front Stone impact - For info
20		Part Position Damages Severity Repair mode	Door sill Back left Dented - For info
21		Part Position Damages Severity Repair mode	Windscreen Front Broken - Lumpsum replacement