


DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZ3CZ ME094614	Brand	VOLKSWAGEN	Maintenance date	04/03/2022
Licence Plate	STU57K	Model	Passat-Variant-CB5-2019	Maintenance mileage	30 754 km
Registration date	30/03/2021	Year	2021	Exterior Color	Other
Odometer	146 705 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	13/05/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Spare key	✗
Charging kit	✗
Service manual holder	✓
User manual	✓
Key	✓
Remote key	✓
Type 2 charging cables	✓

DEKRA Automotive Solutions

Tyres

Goodyear 215/55/17 T Summer 8.0 mm		Goodyear 215/55/17 T Summer 8.0 mm	
Goodyear 215/55/17 W Summer 7.0 mm		Goodyear 215/55/17 W Summer 7.0 mm	

Winter kit

Michelin 215/55/17 T Winter 8.0 mm		Michelin 215/55/17 T Winter 8.0 mm	
Michelin 215/55/17 T Winter 8.0 mm		Michelin 215/55/17 T Winter 8.0 mm	

Damages

1		Part Charging kit Position - Damages Missing Severity - Repair mode Lumpsum replacement	2		Part Spare key Position - Damages Missing Severity - Repair mode Lumpsum replacement
3		Part Complete service track record Position - Damages Missing Severity - Repair mode Lumpsum	4		Part Aftermarket wheel Position - Damages Scratched Severity - Repair mode For info
5		Part Aftermarket wheel Position - Damages Scratched Severity - Repair mode Lumpsum replacement	6		Part Bumper Position Front Damages Scratched Severity - Repair mode Lumpsum Paintworks
7		Part Sill Position Right Damages Scratched Severity - Repair mode Lumpsum Paintworks	8		Part Bumper grille Position - Damages Stone impact Severity - Repair mode For info
9		Part Door Position Front left Damages Scratched Severity - Repair mode Polishing	10		Part Door sill Position Front left Damages Dented Severity - Repair mode For info

DEKRA Automotive Solutions

11		Part: Wing Position: Back left Damages: Dented Severity: - Repair mode: For info	12		Part: Bumper Position: Back Damages: Scratched Severity: - Repair mode: For info
13		Part: Tailgate / Boot door Position: Back Damages: Dented Severity: - Repair mode: Lumpsum repair	14		Part: Wing Position: Back right Damages: Scratched Severity: - Repair mode: For info
15		Part: Door Position: Back right Damages: Dented Severity: - Repair mode: For info	16		Part: Door Position: Front right Damages: Dented Severity: - Repair mode: For info
17		Part: Door sill Position: Front right Damages: Dented Severity: - Repair mode: For info	18		Part: Alloy wheel Position: Front right Damages: Scratched Severity: - Repair mode: For info
19		Part: Bonnet Position: Front Damages: Stone impact Severity: - Repair mode: For info	20		Part: Door sill Position: Back left Damages: Dented Severity: - Repair mode: For info
21		Part: Windscreen Position: Front Damages: Broken Severity: - Repair mode: Lumpsum replacement			