

## VEHICLE INSPECTION REPORT

### Overview

**Order Number**

1001843951

**VIN**

WVWZZZE1XPP509971



Vehicle view - diagonal front left



Vehicle view - diagonal rear right



Interior - driver's side

### Vehicle data

**Make & model**

ID.3 Pro electric 150kW 1-speed 1-speed automatic

**Roadworthy**

Yes

**Vehicle category**

Passenger car

**Vehicle type**

Limousine

**Date of first registration**

28/09/2023

**Interior colour**

Grey

**Exterior colour**

Grey

**Roof colour**

Grey

**Mileage**

10179

**Engine type**

Electric

**Mode of drive**

Front wheel drive

**Number of doors**

5

**Number of seats**

5

**Gearbox**

Automatic

**Number of keys**

2

**Number of cylinders**

4

**Number of gears**

7

### Documents & maintenance

**Next statutory inspection date**

30/09/2027

**Registration certificate available**

No

**Maintenance last mileage****Maintenance booklet**

Yes

**Maintenance last date**

## Vehicle equipment

10-color ambient lighting	Driving on the right
Life	Pro
Part set without country-specific prescriptive standard	Type approval country Italy (San Marino, State of Vatican City)
Operating permit, alteration	4 alloy wheels "East Derry" 7.5J x 18, Black, diamond-turned surface
Ability for online updates starting with ID. software version 2.1	Driver alert system
Regional code " ECE " for radio	CCS vehicle inlet
Mains charging cable for household outlet	No special edition
Without parking assistance/garage parking assist	No special purpose vehicle, standard equipment
Electronic engine sound	Vehicles with special upgrade measures
Car2X	Shock absorption in front
Transmission for electric drive (1-speed)	Torque 310 Nm Base motor is N06/N07/N10
Standard curb weight range	Rear axle weight, standard
Without front cross traffic assist	Battery 320 A (49 Ah)
Tires 215/55 R18	High-voltage battery 62 kWh (gross)
Without camera systems/accident sensors	11 kW AC charging power (alternating current)
Air Care Climatronic 2 zone automatic climate control with enhanced air filter and stationary air conditioning	Refrigerant R1234yf
Maximum DC charging power (direct current) depending on the high-voltage battery pack	Hatchback
Electric motor, system output 150 kW base motor is N06/N07/TB7	Cell module A
Emergency call service; no registration required, service is activated upon delivery	Suspension range 02 installation control only, no requirement forecast
Voice control	Without UN-ECE cybersecurity & software update
Digital radio reception DAB+	Electric motor unit 0EH.A
Without exterior ambient lighting	"East Derry" 7.5J x 18, Black, diamond-turned, tires 215/55 R18
Pedals in stainless steel, with play and pause symbols	Dynamic Road Sign Display
Software network, version 11	Bezel for infotainment display and central controls in Black
Front stabilizer bar	2 USB-C ports in the front, 2 USB-C charging sockets on the center console in rear, charging capacity up to 45 W
Standard manufacturing sequence	ID.3 Life
Elimination of nameplate for engine designation on luggage compartment lid	Rear stabilizer bar
Carpet mats in front and rear	Without specific emission standard
Weight range 5 installation control only, no requirement forecast	With special requirements on the steering column lock
Vehicle class differentiation -10A-	Manual in Italian
Special identification label for EC for M1 passenger vehicles	Standard climatic zones
Surround lighting with welcome light	Without trailer hitch
Disc brakes in front	Rear shock absorption, basic version 1
Electromechanical speed-sensitive power steering	Drum brakes in rear
Tool kit and Tire Mobility Set: 12-volt compressor and tire sealant	Trims for alloy wheels
Rear-wheel drive	Wheel locks with extended theft protection
Driving Mode Selection	First aid kit, warning triangle and safety vest
Without additional tires	Without locking and starting systems
ISOFIX anchors for child seats on outer rear bench seats and on front passenger seat, compatible for i-Size	Standard bumpers
Front seats with height adjustment	Leatherette-wrapped multi-function steering wheel, heated, with touch control
3-point seat belts in front with seat belt pretensioners	Center console with illuminated storage compartment with sliding cover, 2 beverage holders
Door and side trim panel in foam film and woven fabric	3 rear seats, asymmetric split folding rear seat backrest, w/ center armrest, load-through hatch, 2 beverage holders
Tailgate/trunk lid unlocking from outside	Heated front seats
Oncoming vehicle braking when turning and swerve support	Laminated safety glass windshield, heat- and sound-insulating
Green heat-insulating glass windows on sides and in rear	Keyless Start without SAFELOCK
Standard dashboard	Auto-dimming interior rearview mirror
Driver and front passenger airbag with front passenger airbag deactivation	Armrest for front seats
UWB-capable country and carrier frequency, 433.92 to 434.42 MHz	Without special body measures
Transport protection film (minimum protection) with additional transport protection measures	Exterior mirrors: aspherical on driver side, convex on front passenger side
Exterior mirror housings	Gear ratio 11.530
Roof trim strip and air intake and sill in contrasting colors	Curtain airbags in front and rear, side airbags in front, center airbag
Exterior mirrors, power-adjustable, folding and heated, w/ front passenger exterior mirror lowering function	Without decorative films/emblems
Tire Pressure Monitoring System	Lane keeping system Lane Assist
Without lumbar support in seat backrests	Electronic immobilizer
Without extended safety system	Without preparation for VTS (vehicle tracking system)
DC-DC converter 3.0 kW	Platform group class 1
Charging cable mode 3 type 2, 32 A	Navigation system "Discover Pro"
High-beam control Light Assist	Park Distance Control - warning signals for obstacles in the front and rear
Auto. Emergency Braking Front Assist with Pedestrian and Cyclist Monitoring	Without lane change assist
4+1 speakers	Radio "Ready 2 Discover Max"
	LED headlamps with automatic headlight control
	Rain sensor
	Adaptive Cruise Control ACC stop & go incl. speed limiter

Vehicle equipment										
LED rear combination lamps					Single-tone horn					
Diversity antenna for FM reception					Mobile phone interface "Comfort" with inductive charging feature					
Without auxiliary heater/parking heater					Warning signal and warning light for front and rear seat belts not fastened					
Automatically-heated washer nozzles in front					App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto					
Operating voltage 12 V					Equipment options subset for Italy					
Alloy wheels										

Tyres (mounted)										
Make	Location	Position	Type	Rim	Dimensions	Load	Speed	Profile depth	Permitted	Roadworthy
Continental	Front	Left	Summer	Alu	215 18 R55	95	T	5.6 mm	V	V
Continental	Front	Right	Summer	Alu	215 18 R55	95	T	5.5 mm	V	V
Continental	Back	Left	Summer	Alu	215 18 R55	95	T	5.5 mm	V	V
Continental	Back	Right	Summer	Alu	215 18 R55	95	T	5.7 mm	V	V

Spare/emergency tyre & accessories										
Toolkit present			Repair kit present				Compressor present			
No			No				No			
Spare wheel			Temporary spare wheel							
No			No							

Devaluation factors

Nr.	Location	Damage type	Repair type
-----	----------	-------------	-------------

Usage damages

Nr.	Location	Damage type	Repair type
-----	----------	-------------	-------------

Missing parts

Nr.	Location	Damage type	Repair type
1	Tire inflation kit	Missing	Replace
2	Kit gear	Missing	Replace

Mercantile depreciation


<b>Known previous damages</b>	<b>Previous damages detectable</b>	<b>Repainting present</b>
<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="No"/>
<b>Repainting professionally executed</b>	<b>Paint thickness measurement performed</b>	
<input type="text" value="No"/>	<input type="text" value="No"/>	

Notes on the assessment

Vehicle identification :	WVWZZZE1XPP509971
Vehicle condition :	Clean
Inspection condition :	Sunny
Engine test carried out :	Yes
Detail of the assignement and the scope of the assestment :	Cavi di ricarica presenti a bordo.








Commercial pictures





Commercial pictures



Missing parts

Component

Tire inflation kit

Side

1

Component

Kit gear

Side

2